MINIMUM REQUIREMENT

10



WP/SEA MINIMUM REQUIREMENTS Cold Cutting Pipe



	MEMORY JOGGERS
	Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.
\succ	Communicate the "RIGHT TO STOP WORK AUTHORITY POLICY" and is exercised by all crewmembers and other
	personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding.
	The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again.
\succ	Ensure pipe is properly supported.
\succ	Check extension cord(s) for cracks and cuts and take out of service if need be.
\succ	Make sure blade on saw is sharp (before checking blade ensure that saw is not plugged in to power).
\succ	Caution tape cutting area, not allowing anyone near cutting operations.
\succ	Possible equipment damage.
	MINIMUM REQUIREMENTS
1)	Verify All conditions identified in the "Memory Joggers" section are met (or are not applicable); if <u>ANY</u> are not met, <u>STOP</u>
	and add the necessary step to the WP/SEA to ensure the safest method possible.
2)	Route extension cords in such a manner that will not cause tripping hazards.
3)	Support both pieces, when cut, remain stable and will not fall.
4)	Measure and mark pipe to desired length.
5)	Plug in saw and begin cutting on marked line.
6)	Do not rush saw, allow saw to cut using its own weight.
7)	When pipe is cut all the way through, release trigger on saw.
8)	Remove saw and place on the deck, not causing a trip hazard.
9)	Unplug saw and move piece to be installed to designated area.
10)	1 8
11)	Roll up power cord and replace cord, along with saw, to tool house.
12)	
	additionally bleed the surrounding lines if possible.
13)	Pick up jacks and remove caution tape.
14)	
15)	Continue Steps 3 through 10 until job is complete.

ENSURE MINIMUM REQUIREMENTS NUMBERS ARE RECORDED ON WP/SEA