

WP/SEA MINIMUM REQUIREMENTS ELECTRIC DRILL



MEMORY JOGGERS

Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.

- Communicate the "RIGHT TO STOP WORK AUTHORITY POLICY" and is exercised by all crewmembers and other personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding. The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again.
- > Review the scope of work with all crew members to ensure a clear understanding among the crew.
- > Inspect all tools and equipment prior to begin of work
- > Obtain Hot Work Permit if needed and write WP/SEA
- Scan work area for obstructions prior to begin of work.
- > Verify employees are wearing complete PPE.
- > Route all extension cords out of walk ways and caution off if needed.

MINIMUM REQUIREMENTS

- 1) Verify **All** conditions identified in the "Memory Joggers" section are met (or are not applicable); if **ANY** are not met, **STOP** and add the necessary step to the WP/SEA to ensure the safest method possible.
- 2) Inspect all tools and equipment.
- 3) Flag off immediate work area and tag with company name, supervisor contact, and all hazards.
- 4) Check all extension cords for cracks or damage and visually inspect drill for damage.
- 5) Route all extension cords overhead or out of walk ways to prevent tripping hazards.
- 6) Ensure safety glasses or goggles and face shields are worn prior to start of work.
- 7) Watch for prop hand placement and body placement.
- 8) Work at a slow steady pace
- 9) Ensure all clothing is properly tucked in and no loose ends.
- 10) Secure all loose items with tools lanyards to prevent dropped objects.
- 11) Ensure material is properly supported while drilling.
- 12) Return all tools and equipment to their place in tool house.
- 13) Remove all barricades and ensure all barricade tape is in proper container.