

## WP/SEA MINIMUM REQUIREMENTS ELECRTRIC GRINDER



## **MEMORY JOGGERS**

## Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.

- Communicate the "RIGHT TO STOP WORK AUTHORITY POLICY" and is exercised by all crewmembers and other personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding. The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again.
- Review the scope of work with all crew members to ensure a clear understanding among the crew.
- > Inspect all tools and equipment prior to begin of work.
- > Obtain Hot Work Permit if needed and write WP/SEA
- > Scan work area for obstructions prior to begin of work.
- Verify employees are wearing complete PPE.
- > Run extension cords out of walk way and flag off route.
- ➤ Use GFCI in addition with extension cords.

## MINIMUM REQUIREMENTS

- 1) Verify **All** conditions identified in the "Memory Joggers" section are met (or are not applicable); if **ANY** are not met, **STOP** and add the necessary step to the WP/SEA to ensure the safest method possible.
- 2) Inspect all tools and equipment.
- 3) Flag off immediate work area and tag with company name, supervisor contact, and all hazards.
- 4) Ensure safety glasses or goggles and face shields are worn prior to start of work.
- 5) Watch for proper hand placement and body placement.
- 6) Work at a slow steady pace and stand away from sparks.
- 7) Ensure all clothing is properly tucked in and no loose ends.
- 8) Check all extension cords for cracks or damage and visually inspect saw for damage.
- 9) Secure all loose items with tools lanyards to prevent dropped objects.
- 10) Ensure material is properly supported while grinding.
- 11) Support both ends so remaining stable will not fall.
- 12) Return all tools and equipment to their place in tool house.
- 13) Remove all barricades and ensure all barricade tape is in proper container.