





Alert #: SA 14-16

Date: 10/17/2016

## **FOLLOWING POLICIES AND PROCEDURES**

While employees were installing a new line, a line marked for demo was interfering with the process. Employees started to cut the line that was marked for demo and interfering with the job, and realized it was a live line. This resulted in a leak from the line.

## **ROOT CAUSES:**

- Failure to follow procedure/ work plan
  - The pipe was tagged but *not verified* prior to cutting
  - Did not perform Hazard Identification of demo piping
  - No upgrade to WP/SEA
- Failure of the piping Demo Process
  - Piping was flagged for " GIS Demo"
  - Failure to verify demo piping
  - Multiple tasks in a congested area
- Inadequate Work Planning
  - Inadequate scope of work for the day





## **IMPORTANT:**

Not following policies and procedures could lead to potential incidents like the one described here.

## Report all incidents immediately to the HSE department.