

MINIMUM REQUIREMENT



WP/SEA MINIMUM REQUIREMENTS PAINTING



MEMORY JOGGERS

Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.

- Communicate the **“RIGHT TO STOP WORK AUTHORITY POLICY”** and is exercised by all crewmembers and other personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding. The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again.
- Review the scope of work with all crew members to ensure a clear understanding among the crew.
- Make sure an eyewash station and shower are located in the direct proximity of the job.
- Inspect all tools and equipment prior to begin of work
- Always be conscious of the weather and wind direction.
- Select proper tools for the job and inspect for wear or damage.
- Use forklift or crane when setting up heavy objects.
- When using man lift, ensure operator is certified and remain 100% tied off at all times.
- Maintain three point contact when ascending or descending ladders, decks or scaffolds.

MINIMUM REQUIREMENTS

- 1) Verify **All** conditions identified in the “Memory Joggers” section are met (or are not applicable); if **ANY** are not met, **STOP** and add the necessary step to the WP/SEA to ensure the safest method possible.
- 2) Conduct a pre-job meeting prior to beginning work.
- 3) Ensure respirator, goggles, Tyvek suit, paint sock, proper gloves, and ear plugs are worn during painting operations.
- 4) Inspect all equipment and immediate work area for tripping hazards.
- 5) Stage equipment and ensure piping or structural material is free from dust, sand, grease, or any other debris.
- 6) Select proper coatings for the application and mix paint in proper mixing area.
- 7) Take paint to the designated area to wear work is to be done.
- 8) Route all air hoses and ensure pins and whip checks or installed on air hoses.
- 9) When painting place yourself upwind when possible to avoid coming in contact with over spray of paint.
- 10) Turn valve off to air hose to bleed down paint pots.
- 11) Clean paint pots and move out of working area and dispose of excess paint waste in proper waste drums.
- 12) Remove all PPE and dispose of Tyvek suit and gloves and clean off paint with soap and water.
- 13) Return all tools and equipment to their proper place.
- 14) Ensure all waste and debris has been disposed of in its proper place.

ENSURE MINIMUM REQUIREMENTS NUMBERS ARE RECORDED ON WP/SEA