

MINIMUM REQUIREMENT

76



WP/SEA MINIMUM REQUIREMENTS SAND BLASTING



MEMORY JOGGERS

Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.

- Communicate the **“RIGHT TO STOP WORK AUTHORITY POLICY”** and is exercised by all crewmembers and other personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding. The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again.
- Review the scope of work with all crew members to ensure a clear understanding among the crew.
- Make sure an eyewash station and shower are located in the direct proximity of the job.
- Inspect all tools and equipment prior to begin of work
- Always be conscious of the weather and wind direction.
- Select proper tools for the job and inspect for wear or damage.
- Use forklift or crane when setting up heavy objects.
- When using man lift, ensure operator is certified and remain 100% tied off at all times.
- Maintain three point contact when ascending or descending ladders, decks or scaffolds.

MINIMUM REQUIREMENTS

- 1) Verify **All** conditions identified in the “Memory Joggers” section are met (or are not applicable); if **ANY** are not met, **STOP** and add the necessary step to the WP/SEA to ensure the safest method possible.
- 2) Conduct a pre-job meeting prior to beginning work.
- 3) Ensure Tyvek suit, leather or cotton gloves, blasting hood with clean lenses, and ear plugs are worn prior to begin of work
- 4) Inspect all equipment and immediate work area for tripping hazards.
- 5) Stage equipment in designated blast area and make sure work area is free from any tripping hazards.
- 6) Get help when routing air hoses and make sure pins and whip checks are installed on all air hoses.
- 7) When blasting, ensure to blast away for body and ensure stable footing.
- 8) Always blow off material that was blasted before leaving area.
- 9) When returning blasting hoses to hopper, always get help from co-workers.
- 10) Remove all PPE and dispose of Tyvek suit and clean up with soap and water.
- 11) Return blasting hood and gloves to personal lockers.

ENSURE MINIMUM REQUIREMENTS NUMBERS ARE RECORDED ON WP/SEA