



"People First In All We Do"

ALERT NO.: SA 09-11-Re-issue

09/09/2011

SAFETY ALERT

MSA Beam Anchor Model No. 10051455

GIS had been notified of a potential issue with the above beam anchor. The locking pins do not always engage once the anchor is set in place. GIS has notified MSA and are in the process of rectifying this issue.

Immediately remove these beam anchors from service!

These beam anchors need to be sent in and replacements will be sent back out to you. We will be sending the Web Devices sliding beam anchor, Model: BMR150, out to anyone who possesses the MSA Beam Anchors in question. Once the issue has been resolved, we will put the MSA beam anchors back into service. Please contact your supervisor if you are currently using these Anchors.

MSA Beam Anchor Model No. 10051455



Web Devices Sliding Beam Anchor Model No. BMR150



This is the current Beam Anchor to be used by GIS.

