

MINIMUM REQUIREMENT

1



WP/SEA MINIMUM REQUIREMENTS Air Hose Usage



MEMORY JOGGERS

Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.

- Communicate the **“RIGHT TO STOP WORK AUTHORITY POLICY”** and is exercised by all crewmembers and other personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding. The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again.
- Review the scope of work with all crew members to ensure a clear understanding among the crew.
- Inspect all tools and equipment prior to begin of work.
- Obtain Permit to work and write WP/SEA.
- Scan work area for obstructions prior to begin of work.
- Verify employees are wearing complete PPE.
- When routing hoses get help when needed.

MINIMUM REQUIREMENTS

- 1) Verify **All** conditions identified in the “Memory Joggers” section are met (or are not applicable); if **ANY** are not met, **STOP** and add the necessary step to the WP/SEA to ensure the safest method possible.
- 2) Put pins in all connections, whip check must be used between each hose connection.
- 3) Inspect all hose for cuts and cracks.
- 4) Lay hoses out of walkways and flag off.
- 5) Make sure hose is for air use only.
- 6) Wear proper gloves, head gear, eye protection.
- 7) Roll up hoses and return them to proper place in tool house.
- 8) Place all trash and debris into their proper place.

ENSURE MINIMUM REQUIREMENTS NUMBERS ARE RECORDED ON WP/SEA