

MINIMUM REQUIREMENT



WP/SEA MINIMUM REQUIREMENTS CLEANING A LIQUID MUD TANK



MEMORY JOGGERS

Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.

- Communicate the **“RIGHT TO STOP WORK AUTHORITY POLICY”** and is exercised by all crewmembers and other personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding. The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again.
- Review the scope of work with all crew members to ensure a clear understanding among the crew.
- Ensure ample enough secondary containers and oil absorbent rags are on site.
- Make sure an eyewash station and shower are located in the direct proximity of the job.
- Make sure all gangways are secure
- Inspect all tools and equipment prior to begin of work
- Make sure all rescue equipment is in working order and all 30min. bottles and 5min packs are filled.
- Tank monitoring in 15 min. intervals.
- Identify muster station on boat or on dock

MINIMUM REQUIREMENTS

- 1) Verify **All** conditions identified in the “Memory Joggers” section are met (or are not applicable); if **ANY** are not met, **STOP** and add the necessary step to the WP/SEA to ensure the safest method possible.
- 2) Barricade open holes prior to begin of work
- 3) Bring all tools and equipment into the work area. Verify that all tools and equipment are in good working condition.
- 4) Secure all suction hoses with absorbent pads and duck tape.
- 5) All air hoses must be secure with whip checks and pins.
- 6) Make sure all rescue equipment is in working order and on site.
- 7) Ensure confine space permits are completed and posted at work area.
- 8) Perform atmosphere testing before making entry into tanks.
- 9) Entry person must have Tyvek suit, harness and breathing air on prior to entry.
- 10) Perform continuous tank monitoring throughout job.
- 11) Walk entire length of discharge hose to verify the system is leak-free.
- 12) Visit minimum requirement for dispensing recycling wash water plant.
- 13) Shut down air compressor and bleed off all pumps and airlines.
- 14) Verify all tools are clean and properly stored in tool house.
- 15) Ensure work area is clean and trash is disposed of in proper containers.

ENSURE MINIMUM REQUIREMENTS NUMBERS ARE RECORDED ON WP/SEA