



Putting People First Since 1948



**PRODUCT STOP USE AND RECALL / REPLACEMENT NOTICE
IMMEDIATE ACTION REQUIRED**

DBI-SALA Lad-Saf™ Sleeve



Capital Safety/3M recently reviewed the performance of the original Lad-Saf sleeve in the field, including a limited number of incidents involving a serious injury or death in the United States while using the sleeve. Although their review did not reveal product hazard or risk scenarios that would arise in the ordinary and proper use of the product, it did reveal potential misuse scenarios that could result in serious injury or death. The potential misuse scenarios include interference with the braking mechanism (such as entanglement with cords, lanyards, clothing or other materials, or grasping the sleeve prior to or during a fall), or result from the user attaching the sleeve upside down (user inversion). No safety regulator has made a finding that the design of the original Lad-Saf sleeve is defective.

In light of the reported incidents and potential misuse scenarios, Capital Safety/3M has discontinued sale of the original Lad-Saf sleeve, and are voluntarily initiating a full recall of all original Lad-Saf sleeves.

Immediately stop using and quarantine all original Lad-Saf sleeves. Affected part numbers are: 6100016, 6116500, 6116501, 6116502, 6116503, 6116504, 6116505, 6116506, 6116507, 6116509, 6116512, 6116535, 6116540, 6116541, 6116542, 6116500C, 6116500SM, 6116507/A, 6116540b

SAFETY ALERT