



MINIMUM REQUIREMENT

	WP/SEA MINIMUM REQUIREMENTS Rust Removal and Inhibitor Application In Aquatorium	
MEMORY JOGGERS		
Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.		
<ul style="list-style-type: none"> ➤ Communicate the “RIGHT TO STOP WORK AUTHORITY POLICY” and is exercised by all crewmembers and other personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding. The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again. ➤ Ensure proper PPE is donned, i.e., Goggles, Gloves, Hard Hat, Steel Toed Shoes and Dust Mask, at a minimum. ➤ Stay focused when working adjacent to pool. ➤ Open all doors for proper ventilation and to cool pool area. ➤ Stay hydrated, drink plenty of water and sports drinks (4 to 1 ratio). ➤ Take regular breaks when outside temperatures reach 90+ degrees. ➤ When working off ladders, remain 100% tied off at all times. ➤ Ensure ladder is tied off at top rung and ensure co-worker foots ladder when occupied. 		
MINIMUM REQUIREMENTS		
<ol style="list-style-type: none"> 1) Verify All conditions identified in the “Memory Joggers” section are met (or are not applicable); if ANY are not met, STOP and add the necessary step to the WP/SEA to ensure the safest method possible. 2) Have all tools ready for task and inspected for reliability. 3) Place tarp under areas to be scraped. 4) Scrape rust using bar and use brush to smooth over. 5) Wipe scraped and brushed area with cloth to remove remaining sediments. 6) After area has been cleaned of rust, apply rust inhibitor using paint brush, making sure tarp is under areas to be painted. 7) Move to next section. 8) Repeat Steps 3 through 7 until complete. 		