



H S E

HEALTH SAFETY ENVIRONMENTAL




Alert #: 11-18

Date: 8/20/18

Beamers

We have recently had some concern regarding the fall protection beamers we utilize as anchor points. Beamers were sent in primarily due to the retaining collar releasing from the center and sliding to and from on the beamer. We would like to take this time to reassure everyone that this is acceptable, and does not mean that the product is broken or damaged. Below comes directly from our Manufacturer.

- WE DO NOT VIEW THE RETAINING COLLAR RELEASING AS THE PRODUCT BEING “BROKEN” OR “DAMAGED”
- THE COMPRESSED RING IS A CONVENIENCE FEATURE THAT KEEPS THE D RING CENTERED ON THE BAR
- IT IS SPECIFICALLY DESIGNED TO POP AT RELATIVELY LOW LOADS TO MITIGATE CROSS LOADING THE CONNECTOR OR D RING
- ONCE POPPED, THE BEAM SLIDERS NOW WORK AND OPERATE JUST LIKE ANY OTHER BEAMER WITH A FLOATING D RING



Prior to this misunderstanding, we were looking at the newer models of beamers and will start to integrate them into our crew’s equipment as needed. With that said, the beamers pictured above are ok to use and do not need to be sent in for replacement. We will continue to use them as we always have.

If you are working for a Client that would like to purchase different beamers, we will allow our employees to utilize whatever the Client purchases. We would expect that equipment to meet all of the regulatory requirements that our equipment does. If you should have any further questions or concern, please feel free to contact the Corporate HSE department.

***Report all incidents immediately to the Hotline
1-855-543-5163.***

SAFETY ALERT