

## HEALTH SAFETY ENVIRONMENTAL



Alert #: SA 31-22 Date: October 3, 2022

## New 1" Hoses Separating from Coupling

We have recently identified an issue with the 1" air hoses purchased through our NuWave division. Several air hoses were sent out to an offshore location where they had two clamp failures due to the hose separating from the hydraulic clamp. Please perform a very thorough hose inspection, paying close attention to 1" hose connections. If you find any issues with the coupling or if you find that the hose is slipping out, please remove the hose from service, and order the replacement.





Report all incidents immediately to the GIS Hotline 1-855-543-5163.