



**WP/SEA MINIMUM REQUIREMENTS  
Tie Wrapping Cables**



**MEMORY JOGGERS**

**Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.**

- Communicate the **“RIGHT TO STOP WORK AUTHORITY POLICY”** and is exercised by all crewmembers and other personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding. The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again.
- Dropping tools onto people below, into running equipment.
- Cuts from cut ends of ty-raps.
- Cinching ty-wraps to tight tearing into cables.

**MINIMUM REQUIREMENTS**

- 1) Verify **All** conditions identified in the “Memory Joggers” section are met (or are not applicable); if **ANY** are not met, **STOP** and add the necessary step to the WP/SEA to ensure the safest method possible.
- 2) Rope off work area to prevent them from being hit by tools that are dropped.
- 3) Clean up all cut ty-wrap ends off ground to prevent slipping.
- 4) Prevent over tightening and tearing into cables.
- 5) Wear gloves to prevent cuts from sharp ends.
- 6) Wear safety glasses to prevent eye injury from flying cut ends.
- 7) 100% tie off when working in elevated locations.