

MINIMUM REQUIREMENT

15



WP/SEA MINIMUM REQUIREMENTS Demo of Electric Cable



MEMORY JOGGERS

Ensure that the following conditions are met before proceeding. If not met, address on WP/SEA.

- Communicate the **“RIGHT TO STOP WORK AUTHORITY POLICY”** and is exercised by all crewmembers and other personnel that believe something or some condition has changed. The job is to be stopped and accessed before proceeding. The WP/SEA may need to be modified or a new WP/SEA maybe required before starting the work task again.
- Unintended Shutdown of Equipment.
- Electrical Shocks/ Blow out.
- Cuts or puncture on hands.
- Injury from falls

MINIMUM REQUIREMENTS

- 1) Verify **All** conditions identified in the “Memory Joggers” section are met (or are not applicable); if **ANY** are not met, **STOP** and add the necessary step to the WP/SEA to ensure the safest method possible.
- 2) Flag off area with danger tape and install tags with company name, supervisor contact number, and list all hazards
- 3) Route extension cord in such a manner that will not cause tripping hazards, Install GFCI.
- 4) Ensure fire extinguisher is on site
- 5) Wear fall protection when working at heights greater than six foot
- 6) Ensure all cables to be demo are LOTO and checked with meter on both AC and DC to ensure no voltage.
- 7) Ensure all cables are verified and marked and start demo from one end at 5’ sections as not to get confused and cut wrong cable.
- 8) Begin cutting cable or conduit into sections that are easily manageable.
- 9) Wear proper PPE to prevent injury from cut cables.
- 10) Keep work area and walkways clear of trash and debris.
- 11) Remove all barriers, trash and debris
- 12) Dispose of cable or conduit into proper storage bins.

ENSURE MINIMUM REQUIREMENTS NUMBERS ARE RECORDED ON WP/SEA