



H S E

HEALTH SAFETY ENVIRONMENTAL



Alert #: SA 04-25

Date: January 30, 2025

Potential Dropped Object From Cargo Basket

While offloading a boat offshore, the lifting and rigging team noticed a rock lodged into the bottom of a cargo basket between the floor and the support gussets on the frame. This basket was shipped from one of our facilities. The rock measured approximately 5 inches wide on each side and weighed over 4 pounds. If the rock would have worked loose while being lifted, it could have had very serious consequences.

Corrective actions:

- Flag man on the task called stop work to secure the load.
- The rock was removed from the cargo basket using a pry bar.
- On-site HSE was notified before continuing lifting operations.

Key Takeaways

- Review Load Securement Policy as needed prior to moving loads.
- Utilize LLCF-046-Load Securement Checklist
- Utilize LLCF-057 Pre-Shipping Checklist
- Ensure debris and unsecured objects are removed from loads prior to lifting



SAFETY ALERT