



H S E

HEALTH SAFETY ENVIRONMENTAL



Alert #: SA 28-23

Date: July 31st, 2023

BEING AWARE OF YOUR SURROUNDINGS

While pressure washing on a deck, an employee was walking by a cutting box. While walking by, there was a cotter pin that was protruding from where the slings tied into. Since the employee was unaware of the presence of the cotter pin, the pin had cut him upon the upper area of his chest while he was walking by it.



Lesson Learned:

Always be aware of your surroundings.

Before conducting any form of work, a thorough and careful scan of the working environment should be done as to mitigate any possibility of any accidents happening. In order to prevent accidents like this from occurring again in the future, it is highly important that all employees remain aware of where they are working and how they plan on approaching any work.

**Report all incidents immediately to the GIS Hotline
1-855-543-5163**

Following your initial phone call, an incident report **must** be completed and e-mailed to:
incident@gisy.com

SAFETY ALERT